

BMW Dealer Principals, Sales Managers, Service Managers, and Parts Managers

A Delivery Stop has been issued by BMW AG to correct a potential problem with the engine oil pump on certain S63TU-equipped vehicles. Affected vehicles are the 2013 Model Year M5, M6 Coupe, and M6 Convertible. Vehicles equipped with an affected pump could experience a sudden loss of oil pressure which will result in severe engine damage.

BMW Customer Relations is contacting customers that have already taken delivery and recommending customers not drive the vehicle. A Q&A will be provided to all BMW dealers in the form of an additional DCS message later today. This Q&A will provide you with the necessary information to answer your customers' concerns.

Vehicles included in the accompanying VIN list must **not** be delivered until the repairs are completed.

Do not order any parts at this time.

Sincerely,

**Technical Service** 

Attachments:

Delivery Stop VINS[80ec98e2].pdf

Recipients: BMW Passenger Cars, All Offerings, All Regions, All Areas, Service, All BMW Passenger Cars, All Offerings, All Regions, All Areas, Sales, All

BMW Passenger Cars, All Offerings, All Regions, All Areas, Parts, All

Close Window Print Message