Enter Chassis Number:

D592954

Submit

**New Inquiry** 



CONFI

THIS DOCUMENT IS NOT TO BE USED OR RELIED UPON FOR IMPORT OR EXPORT PURPOSES AND IS NOT TO BE DISTRIBUTED OR SHARED WITH THIRD PARTIES \*EXCEPT FOR SPECIFIC INFORMATION THAT MAY BE REQUIRED BY LAW

DO NOT USE DAVIS AS THE SOLE INDICATOR FOR CALCULATING VEHICLES' DAYS OUT OF SERVICE. DAVIS IS A GUIDE ONLY AND DOES NOT INCLUDE EXACT NUMBERS AS CONFLICTS IN DAYS TO CLOSE A REPAIR ORDER © 2018 BMW of North America, LLC

Note: All dates in this report are in the MM DD YYYY Format.

### Vehicle Data

WBSFV9C52ED592954

Chassis Number: D592954

> 01 - BMW Car Line Make:

Model Year: 2014

AG Model Code/Desc: FV93 - M5 Sedan NA Model Code/Desc: 145G - M5 Sedan

Motor Type: S63T

**Exterior Color Code:** 300 (Alpine White)

LKSW (Black Extended Merino Interior Trim Code:

M\$RP:

Leather)

\$115,425.00

DAVIS #: 17

Assist Safety Plan expires: Assist Conv. Plan expires: 00/00/0000 00/00/0000

TCU ESN / TCU IMEI:

357511041451787

TCU MIN:

XXX-XXX-XXXX

MDN / MSISDN:

XXX-XXX-XXXX

Vehicle Production Date:

2013/09

Series: F10

Wholesale Center ID/Loc: 21188 - 01

Wholesale Date:

11/12/2013

Retail Center ID/Loc:

21188 - 01 03/30/2014

**Retall Date:** In-Service Date:

03/30/2014

MP Claims

VEHICLE COMMENTS

Campaign Summary

#### NO OPEN CAMPAIGNS

## **Option Information**

| Code | Description                   | Code | Description                    |
|------|-------------------------------|------|--------------------------------|
| 0ZCP | Competition Package           | 0ZDB | Driving Assistance Plus        |
| 0ZEC | Executive Package             | 0ZLP | Lighting Package               |
| 01CA | CO2 relevant vehicles         | 02NZ | 20" M forged alloy wheels      |
| 02VB | Tire pressure monitor         | 0319 | Universal garage-door opener   |
| 03AG | Rear view camera              | 0423 | Floor mats                     |
| 0430 | Auto-dimming mirrors          | 0431 | Auto-dimming rearview mirror   |
| 0464 | Ski bag                       | 0465 | Split fold-down-rear seat      |
| 0488 | Lumbar support                | 04CE | Anthracite Wood Trim           |
| 04M8 | Rear seat reading lights      | 04MA | Multi-function seats w/lumbar  |
| 0508 | Park Distance Control         | 0575 | Additional 12-V power sockets  |
| 05AP | Decoding for no-dazzle hgh bm | 0609 | Navigation system w/ touchpad  |
| 0696 | 6-Disc DVD Changer            | 0697 | DVD Area coding, North America |
| 06AC | BMW Assist eCall              | 06AE | BMW TeleServices               |

| 06AK | BMW Online and BMW Apps        | 06AM | Advanced RTTI                  |
|------|--------------------------------|------|--------------------------------|
| 06AP | Remote Services                | 06F2 | Bang Olufsen Sound System      |
| 06NR | BMW Apps - iOS and Android     | 06NS | Enhanced B/T and Smartphone In |
| 0754 | Rear spoiler                   | 0776 | Anthracite Alcantara Headliner |
| 08KL | Oil Chg 10,000 mls/12 months   | 08S4 | Variable Light Decoding        |
| MT80 | Daytime driving lights on engi | 08TN | Daytime driving lights         |
| 0925 | Shipping package               | 09AA | Transport protection           |

## Warranty/Maintenance Programs/Contract Services(Administered by BMW NA)

| Туре | Warr/Program<br>Codes/Desc                       | Contract<br>Number/<br>Status   | Eff<br>Date | Enrollment<br>Date | No<br>Coverage<br>As Of | Exp<br>Age<br>(Mth) | Exp<br>Odometer<br>(Miles) | Current<br>Age<br>(Mth) | Retail<br>Center | Center<br>Name | Vende<br>Code<br>Used |
|------|--|---|-------------|--------------------|-------------------------|---------------------|----------------------------|-------------------------|------------------|----------------|-----------------------|
|      | New Vehicle<br>Limited Warrant                   | 0000000<br>ACTIVE   | 03/30/2014  |                    | 03/30/2018              | 48                  | 50,000                     | 47                      |                  |                |                       |
| FE   | Federal<br>Emissions 8/80<br>FE 96 MO/80K<br>MLS | 0000000<br>ACTIVE   | 03/30/2014  | 03/30/2014         | 03/30/2022              | 96                  | 80,000                     | 47                      | 21188            | Irvine<br>BMW  | 00                    |
| CA   | California<br>Emissions                          | Vehicle may qualify for California Emissions Coverage. Please verify if the vehicle was sold or is registered in Emissions Covered State (AZ,CA,CT,DE,MA,MD,ME,NJ,NM,NY,OR,PA,RI,VT,WA). Please confirm model yeard current registration of the vehicle and click here to determine coverage. |             |                    |                         |                     |                            |                         |                  |                |                       |

# Repair History (Claims)

| Center<br>ID | Loc<br>ID | Claim<br>Number | Repair<br>Order<br>Number | Repair<br>Order<br>Date | Repair<br>Entry<br>Date | DAVIS<br># | ∕iileage | Defect Code/Description  |
|--------------|-----------|-----------------|---------------------------|-------------------------|-------------------------|------------|----------|--|
| 44013        | 01        | 45390           | 9713                      | 08/31/2017              | 09/06/2017              | 1          | 37,270   | 61610077MP FT WIPER RUBBER INSERT-MP<br>6400315900 Cooling operation too low / deep / slight<br>64310237MP MICROFILTER REPLACEMENT<br>85990091MP OIL SERVICE(MP)AFTER THE 1ST<br>85990101MP VEHICLE CHECK<br>85990501MP STANDARD OPERATION MP  |
| 44013        | 01        | 11860           | 2994                      | 09/28/2016              | 09/29/2016              | 3          | 31,801   | 5124002900 Boot lid lock with microswitch sticking/jammec  |
| 44013        | 01        | 8120            | 1995                      | 08/08/2016              | 08/18/2016              |            | ŕ        | 11720376MP ENG AIR FILTER-DIRTY-MP 34000077MP BRAKE FLUID CHANGE- FULL MAINTENAN 34210077MP RR BRAKE PADS - MAINTENANCE PLAN 6213901800 E8x E9x Fx R5x R60 CBS Data for brake pad incorrect usage 85990091MP OIL SERVICE(MP)AFTER THE 1ST 85990201MP MAINTENANCE SERVICE, SPARK PLUGS 85990501MP STANDARD OPERATION MP |
| 21181        | 01        | 67620           | 255020                    | 09/25/2015              | 09/25/2015              |            |          | 0011450300 B111714: Retrofit Heat Insulators to Turbo Ch<br>Lines  |
| 21181        | 01        | 67610           | 255020                    | 09/25/2015              | 09/25/2015              |            |          | 3234013900 Airbag unit, steering wheel unpleasant noises 3435001800 CBS data of brake pad wear, incorrectly calcumileage/km Incorrect/incomplete reading 64310237MP MICROFILTER REPLACEMENT 85100256MP Battery Swap Program MP 85990091MP OIL SERVICE(MP)AFTER THE 1ST 85990501MP STANDARD OPERATION MP                |
| 21188        | 01        | 365890          | 144715                    | 10/23/2014              | 10/24/2014              | 0          | 12,770   | 85990091MP OIL SERVICE(MP)AFTER THE 1ST<br>85990501MP STANDARD OPERATION MP  |
| 21188        | 01        | 178830          | 125379                    | 04/16/2014              | 04/17/2014              | 0          | 1,381    | 85990088MP 1200 MI SERV -M5,Z8,S54B32 M3<br>85990501MP STANDARD OPERATION MP   |
| 21188        | 01        | 46850           | 109890                    | 11/18/2013              | 11/19/2013              | 0          | 6        | 11999977BV QCI SPOT DELIVERY   |

New Inquiry

PRINT

Retail Pricing Inf